

We shape a safe, high quality, sustainable and friendly built environment.

Our Ref: BCA BC 15.0.3

2 May 2012

Building Engineering Division (#05-00)

Fax : 6325 7482 DID : 6325 7493

E-mail: andris_leong@bca.gov.sg

See Distribution

Dear Sir/Madam

SUPERVISION OF BUILDING STRUCTURAL WORKS

We have received feedback from the industry that some site supervisors are not present at the sites to provide supervision of structural works, especially critical structural works that require immediate supervision. Examples of critical structural works include concreting, piling, pre-stressing, tightening of high-friction grip bolts. Failure to supervise structural works is an offence under the Building Control Act.

- We like to remind Qualified Persons (QPs) for structural works that site supervisors work under their supervision and direction. Hence, it is the responsibility of the QP for structural works to ensure that his appointed site supervisors are at the site to supervise the structural works. The site supervisor too has a responsibility to inform the QP for structural works if he or she, for whatever reason, is not able to supervise the structural works. In such circumstances, the QP for structural works shall arrange to station an accredited site supervisor as temporary replacement on site and inform BCA of such temporary arrangement.
- 3 Site supervisors are to ensure that the builder carries out the structural works in accordance with the approved structural plans. Prior approval from BCA is required before any major deviation to the structural plan is to be carried out. If deviations from approved structural plans are to be implemented on site, there should be a written consent from the QP. One particular area commonly overlooked is the construction of earth-retaining and stabilising structure (ERSS) for supporting the face of an excavation made for the purpose of constructing any pile cap, footing, sump, lift pit or trench if it exceeds 10 square metres in area or 2 metres in depth. Such ERSS work requires the submission of plans for approval. Site supervisors should report to BCA if excavation is carried out prior to obtaining approval of ERSS plan or not in accordance with the approved ERSS plan.

- BCA has taken prosecution action against QPs and site supervisors for contravening the building regulations. Some past prosecution cases include QP being convicted for permitting builder to carry out structural work without approved plans, site supervisors for failure to supervise the structural works in accordance with the approved structural plans, and failure to provide immediate supervision for critical structural works, such as concreting and piling works. The errant site supervisors were also suspended for 3 months by the IES-ACES Joint Accreditation Committee. BCA would like to work together with the QPs and site supervisors to ensure building safety during construction and they should report to BCA should there be any contravention of building regulations found on site.
- We would appreciate it if you could disseminate the contents of this circular to your members. Please contact Mr Shee Siu Ming at Tel. 63257583 or email: shee siu ming@bca.gov.sg if you need further clarification. Thank you.

Yours faithfully

ANDRIS LEONG (MS) DEPUTY DIRECTOR

BUILDING ENGINEERING DIVISION

for COMMISSIONER OF BUILDING CONTROL

DISTRIBUTION (via e-mail):

ASSOCIATIONS / SOCIETIES

PRESIDENT
INSTITUTION OF ENGINEERS, SINGAPORE (IES)
70, BUKIT TINGGI ROAD
SINGAPORE 289758
ies@iesnet.org.sq

PRESIDENT
ASSOCIATION OF CONSULTING ENGINEERS, SINGAPORE (ACES)
18 SIN MING LANE
#06-01 MIDVIEW CITY
SINGAPORE 573960
secretariat@aces.org.sq

PRESIDENT
SINGAPORE CONTRACTORS ASSOCIATION LIMITED (SCAL)
CONSTRUCTION HOUSE
1 BUKIT MERAH LANE 2
SINGAPORE 159760
enquiry@scal.com.sq

PRESIDENT
SINGAPORE INSTITUTE OF ARCHITECTS (SIA)
79 NEIL ROAD
SINGAPORE 088904
info@sia.org.sg

PRESIDENT SOCIETY OF PROJECT MANAGERS (SPM) MACPHERSON ROAD P.O.BOX 1083 SINGAPORE 913412 sprojm@yahoo.com

PRESIDENT
SINGAPORE INSTITUTE OF BUILDING LIMITED (SIBL)
70 PALMER ROAD,
#03-09C PALMER HOUSE
SINGAPORE 079427
josephine@sib.com.sq

PRESIDENT
REAL ESTATE DEVELOPERS' ASSOCIATION OF SINGAPORE (REDAS)
190 CLEMENCEAU AVENUE
#07-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
enquiry@redas.com

PRESIDENT
SINGAPORE INSTITUTE OF SURVEYORS & VALUERS (SISV)
110 MIDDLE ROAD #09-00
CHIAT HONG BUILDING
SINGAPORE 188968
sisv.info@sisv.org.sq

PRESIDENT
SINGAPORE STRUCTURAL STEEL SOCIETY (SSSS)
1 LIANG SEAH STREET
#02-11/12 LIANG SEAH PLACE
SINGAPORE 189022
secretariat@ssss.org.sq

PRESIDENT
GEOTECHNICAL SOCIETY OF SINGAPORE
C/O PROFESSIONAL ACTIVITIES CENTRE
NUS FACULTY OF ENGINEERING
9 ENGINEERING DRIVE 1
SINGAPORE 117576
geoss@nus.edu.sq

PRESIDENT
PROFESSIONAL ENGINEERS BOARD, SINGAPORE (PEB)
1ST STOREY, TOWER BLOCK, MND COMPLEX
5 MAXWELL ROAD
SINGAPORE 069110
registrar@peb.gov.sq

PRESIDENT
BOARD OF ARCHITECTS (BOA)
5 MAXWELL ROAD
1ST STOREY TOWER BLOCK
MND COMPLEX
SINGAPORE 069110
boarch@singnet.com.sq

DIRECTOR
PROTECTIVE INFRASTRUCTURE & ESTATE
DEFENCE SCIENCE & TECHNOLOGY AGENCY
1 DEPOT ROAD #03-01J
SINGAPORE 109679
Icheehio@dsta.gov.sq

DEPUTY DIRECTOR
PROJECT DEVELOPMENT & MAINTENANCE BRANCH
MINISTRY OF EDUCATION
1 NORTH BUONA VISTA DRIVE
OFFICE TOWER LEVEL 9
SINGAPORE 138675
eng wee tong@moe.gov.sq

DIRECTOR
BEST SOURCING DEPARTMENT
PUBLIC UTILITIES BOARD
40 SCOTTS ROAD #18-01
ENVIRONMENT BUILDING
SINGAPORE 228231
koh boon aik@pub.gov.sq

DEPUTY CHIEF EXECUTIVE
INFRASTRUCTURE & DEVELOPMENT
LAND TRANSPORT AUTHORITY
1 HAMPSHIRE ROAD
BLOCK 8 LEVEL 1
SINGAPORE 219428
bok ngam lim@lta.gov.sg

HEAD
TECHNICAL RESOURCE
BUILDING QUALITY DEPARTMENT
HOUSING & DEVELOPMENT BOARD
HDB HUB
480 LORONG 6 TOA PAYOH
SINGAPORE 310480
hkc1@hdb.gov.sq

DIRECTOR
ENGINEERING PLANNING DIVISION
JTC CORPORATION
THE JTC SUMMIT
8 JURONG TOWN HALL ROAD
SINGAPORE 609434
chwee.koh@itc.gov.sg

DIRECTOR
BUILDING
PEOPLE'S ASSOCIATION
9 STADIUM LINK
SINGAPORE 397750
foo soon leng@pa.gov.sq

PRESIDENT
THE TUNNELLING AND UNDERGROUND
CONSTRUCTION SOCIETY SINGAPORE (TUCSS)
C/O CMA INTERNATIONAL CONSULTANTS PTE LTD
1 LIANG SEAH STREET
#02-12 LIANG SEAH PLACE
SINGAPORE 189022

info@tucss.org.sq

PRESIDENT
SOCIETY OF ROCK MECHANICS AND ENGINEERING GEOLOGY
1 LIANG SEAH STREET
#02-12 LIANG SEAH PLACE
SINGAPORE 189022
srmeq@cma.sq

ALL CORENET E-INFO SUBSCRIBERS